

September 14, 2016

United States Environmental Protection Agency
Air Compliance Branch
290 Broadway, 21st Floor
New York, NY 10007-1866

Attn: NESHAP COORDINATOR

Re: STEWART INTERNATIONAL AIRPORT – BUILDING #: 110


OPERATION PROJECT #: 206.006

Dear Madam/Sir:

Our courtesy notification for the asbestos abatement work to be done at the above referenced location is attached.

If you have any questions, please contact me at 201-595-4881.

Sincerely,



Uday Mehta, Manager
Environmental field Operations
Construction Management Division

Cc: Project File (EPA-2476)
RACM Notification File

UM/fl

**U.S. Environmental Protection Agency
Notification of Demolition and Renovation**

Operator Project #: 206.006		Postmark:		Date Received: 08/24/2016		Notification #: EPA-2476	
I. Type of Notification (O=Original R=Revised C=Canceled) O / 2							
II. Facility Information (Identify owner, removal contractor, and other operator)							
Owner Name: THE PORT AUTHORITY OF NY & NJ							
Address: 241 ERIE ST. ROOM 236							
City: JERSEY CITY		State: NJ		Zip: 07310			
Contact: F.DAMBREVILLE, FACILITY SUPERVISOR, ENVIRONMENTAL FIELD OPS		Telephone: 718-533-4053					
Removal Contractor:BNK RESTORATION CO., INC.							
Address: 223 RANDOLPH AVENUE							
City: CLIFTON		State: NJ		Zip: 07011			
Contact: ALEKSANDAR KURIDZA		Telephone: 973-478-4681					
Other operator: N/A							
Address:							
City:		State:		Zip:			
Contact:		Telephone:					
III. Type of Operation (D=Demo O=Ordered Demo R=Renovation E=Emergency) R							
IV. Is Asbestos Present? (Yes/No) YES							
V. Facility Description (include building name, number, floor, and /or room number):							
Building Name: AIRPORT OPERATIONS FACILITY							
Address: STEWARD INTERNATIONAL AIRPORT							
City: NEW WINDSOR		State: NY		County: ORANGE			
Site Location: BUILDING # 110							
Building Size: N/A		# of Floors: 1		Age in Years: N/A			
Present Use: MULTIPLE USE				Prior Use: MULTIPLE USE			
VI. Procedure, Including Analytical Method, If Appropriate, Used to Detect the Presence of Asbestos Material: BULK SAMPLING WITH TEM ANALYSIS							
VII. Approximate Amount of Asbestos, Including: 1. Regulated ACM to be Removed 2. Category I ACM Not Removed 3. Category II ACM Not Removed			Non-RACM To Be Removed	RACM to Be Removed	Nonfriable Asbestos Materials Not To Be Removed		Indicate Measurement
					Cat I	Cat II	
Pipes FITTINGS/ CAULKING/COMPOUND			300 LN.FT	40 LN.FT			Lnft: 340
Surface Area MASTIC/CEMENT BOARD			15880 SQ.FT	20 SQ.FT			Sqft: 15,900
Vol RACM Off Facility Component							Cuft: 0
VIII. Scheduled Dates Asbestos Removal				Start: 09/19/2016		Complete: 12/30/2016	
IX. Scheduled Dates Demo\Renovation				Start:		Complete:	

**U.S. Environmental Protection Agency
Notification of Demolition and Renovation**

EPA-2476

X. Description of Planned Demolition or Renovation Work, and Method(s) to Be Used:

REMOVAL USING WET METHOD WITH SURFACE AND ISOLATION BARRIERS

XI. Description of Work Practices and Engineering Controls to Be Used to Prevent Emissions Of Asbestos

At the Demolition And Renovation Site:

DUST CONTROL USING WET METHOD ISOLATION AND SURFACE BARRIER, ENGINEERING CONTROL USING VACUUMS EQUIPPED WITH HEPA FILTERS. WET REMOVAL AS PER NEW YORK STATE INDUSTRIAL CODE RULE 56

XII. Waste Transporter #1

Name: TRI-STATE TRANSFER ASSOCIATES

Address: 1199 RANDALL AVENUE

City: BRONX

State: NY

Zip: 10474

Contact: JAIME BYRNE BARANOFF

Telephone: 718-617-0771

Waste Transporter #2

Name: N/A

Address:

City:

State:

Zip:

Contact:

Telephone:

XIII. Waste Disposal Site

Name: MINERVA ENTERPRISES

Location: 8955 MINERVA ROAD, SE

City: WAYNESBURG

State: OH

Zip: 44688

Telephone: 330-866-3435

XIV. If Demolition Ordered By a Government Agency, Please Identify the Agency Below

Name:

Title:

Authority:

Date of Order:

Date Ordered To Begin:

XV. For Emergency Renovations

Date and Hour of Emergency:

Description of Sudden or Unexpected Event:

Explanation of How the Event Caused Unsafe Conditions or Would Cause Equipment Damage or an Unreasonable Financial Burden:

XVI. Descriptions of Procedures to Be Followed in the Event That Unexpected Asbestos Is Found or Previously Nonfriable Asbestos Material Becomes Crumbled, Pulverized or Reduced to Powder:


IMMEDIATE ISOLATION OF THE AREA AND ADEQUATE WETTING OF ASBESTOS MATERIAL FOLLOWED BY HEPA VACUUMING AND WET WIPING ALL AFFECTED AREAS

XVII. I Certify That an Individual Trained in the Provisions of This Regulation (40 CFR Part 61, Subpart M) Will Be On-Site During the Demolition or Renovation And Evidence That the Required Training Has Been Accomplished by This Person Will Be Available for inspection


(Signature of Owner/Operator)

09-14-16
(Date)

XVIII. I Certify That the Above Information Is Correct.


(Signature of Owner/Operator)

09-14-16
(Date)